Oil Field Environmental Incident Summary

Responsible Party: HESS BAKKEN INVESTMENTS II, LLC
Well Operator: HESS BAKKEN INVESTMENTS II, LLC

Well Name: EN-MOLLET-158-93- 2019H-1

Field Name: EAST TIOGA Well File #: 17074

Date Incident:6/25/2015Time Incident:20:35Facility ID Number:County:MOUNTRAILTwp: 158Rng: 93Sec: 20Qtr:

Location Description: NDIC Verbal Notification completed at 08:28 (a.m.) (06-26-2015) - NDDH

Verbal Notification completed at 08:39 (a.m.) (06-26-2015)

Submitted By: Alex Beach Received By:

Contact Person: Jason Henry

3015 16th Street SW, Suite 20

Minot, ND 58701

General Land Use: Well/Facility Site

Affected Medium: Topsoil

Distance Nearest Occupied Building:0.8 MileDistance Nearest Water Well:0.8 Mile

Type of Incident: Tank Leak

Release Contained in Dike: No Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil 4 Barrels

Brine 250 Barrels

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

At this time are no reasons to suspect any atmospheric or health hazards.

Areal Extent:

Potential Environmental Impacts:

The potential environmental impacts are to the well/facility soils as well as the soils off site that were impacted by the fluids leaving the site during the time of the release.

Action Taken or Planned:

The site has been shut in, and the load lines have been locked out. There will be some removal of material from within the boundaries of the site. For the offsite impacts, the saturated soil will be removed and soil borings and samples will be taken to determine further scope of work. If any ground water is discovered during initial excavation work, more aggressive methods will be taken at a sooner time rather than waiting for samples.

Wastes Disposal Location: The waste will be disposed of at an apporved waste disposal facility

Agencies Involved: Local Law Enforcement

U			

Date: 6/26/2015 Status: Reviewed - Follow-up Required Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill impacted areas off of location. Follow-up is necessary.

Date: 7/29/2015 Status: Inspection Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 7/29/2015. Impacted material has been excavated and removed with a sump placed in the area with the highest amount of impact. Erosional control buffers have been placed in the excavated area. Follow-up is necessary to ensure grass is coming back and the site is returning to pre-spill conditions.

Date: 10/14/2015 Status: Inspection Author: Kangas, Kathleen

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

On site at 9:45 a.m. Sunny, 45 degrees, light wind. Grass growth seen in all off-site areas. No areas of bare grass seen.